






















230-000091


1  x2	2  x1	3  x1	4  x1	5  x1
6  x1	7  x1	8  x1	9  x1	10  x2
11  x2	12  x1	13  x1	14  x1	15  x1
16  x1	17  x1	18  x1	19  x1	20  x1
21  x1	22  x1	23  x1	24  x1	25  x1
26  x1	27  x1	28  x1	A (6.3X50)  x22	B  C  x22
D  x2	E  x6	F (3.5X12)  x40	G   x3	I  x10
K  x1	L (4X16)  x18	M(5X50)  x8		

Step 1



A x6


Step 2



B x2


C x2

Step 3



A x8



Step 4



B x8

C x8

Step 5




B x4

M x8


C x4

Step 6




D x2

Step 7




A x8

Step 8




Step 9



B	x8
---	----

C	x8
---	----


Step 10



F	x20
---	-----

L	x12
---	-----


Step 11



F	x14
---	-----

L	x6
---	----

Step 12



J	x10
---	-----

Complete

