


069-000101

Assembly Drawing

TOOLS




X32


X16

X1




X10 M6*30

X12



X24





No:	Specification (W*D*H)	QTY
①	1798*662*18	1
②	662*560*18	2
③	898*325*18	1
④	900*300*25	1
⑤	1798*325*18	1
⑥	560*325*18	2
⑦	1760*100*18	1
⑧	540*100*18	2
⑨	325*230*18	2
⑩	1800*582*25	1





STEP:1




STEP:2





STEP:3



STEP:4



STEP:5



STEP:6